



Vacuum side

Vacuum chamber

O-Ring

Welding possible

Non-Vacuum side

O-Ring compression is correct when nut is fixed flat onto the vacuum chamber, no additional torque required.